

# LIDDELL

## GLENCORE

Date	Time	Location	<u>Chain of ponds</u>		<u>Burlings</u>		<u>Scrivens</u>		<u>Sub Station</u>	
			Ground Vibration (mm/s)	Over pressure (dBL)	Ground Vibration (mm/s)	Over pressure (dBL)	Ground Vibration (mm/s)	Over pressure (dBL)	Ground Vibration (mm/s)	Over pressure (dBL)
4/8/2020	12:37	Entrance Pit	0.53	111.5	0.02	108.9	0.03	110.1	0.28	109.1
6/8/2020	12:55	Entrance Pit	1.03	106.3	0.1	84.6	0.07	96.3	0.71	102.7
7/8/2020	12:22	South Pit	0.53	110.8	0.03	102.8	0.03	106.9	0.36	110.7
13/8/2020	12:54	South Pit	0.21	99.2	0.01	100.2	0.02	89.7	0.07	96.7
14/8/2020	12:26	Bayswater Pit	0.55	111.8	0.02	92.9	0.02	98.7	0.25	110
18/8/2020	15:34	Bayswater Pit	4.6	120.8	0.1	92.4	0.1	89.7	2.39	120.1
21/8/2020	12:34	South Pit	0.22	109.9	0.02	104.3	0.02	101.4	0.15	108.3
21/8/2020	12:55	Entrance Pit	1.79	112.8	0.04	107.5	0.03	101.6	0.65	109.7
25/8/2020	13:07	South Pit	1.74	105.3	0.17	88.8	0.08	93	0.82	100.7