

LIDDELL

GLENCORE

Date	Time	Location	Chain of ponds		Burlings		Scrivens		Sub Station	
			Ground Vibration (mm/s)	Over pressure (dBL)	Ground Vibration (mm/s)	Over pressure (dBL)	Ground Vibration (mm/s)	Over pressure (dBL)	Ground Vibration (mm/s)	Over pressure (dBL)
1/9/2020	15:32	Bayswater Pit	0.26	100.9	0.01	90.3	0.02	92.2	0.11	101.5
2/9/2020	9:02	Entrance Pit	0.61	107.2	0.02	97.6	0.02	100	0.3	105
7/9/2020	12:53	Bayswater Pit	1.38	101.1	0.11	86.8	0.09	95.8	0.65	100.8
8/9/2020	13:18	Entrance Pit	0.37	94.6	0.05	81.9	0.03	83	0.16	93.6
10/9/2020	13:01	South Pit	8.72	122.8	0.05	99.9	0.03	97.5	1.36	123
14/9/2020	12:59	Entrance Pit	0.51	99	0.05	91.6	0.05	88.3	0.38	96.8
18/9/2020	12:25	South Pit	3.17	116.8	0.11	98.6	0.06	97.2	1.95	116.4
21/9/2020	9:02	Entrance Pit	0.8	102.9	0.15	86	0.09	92.7	0.96	101.5
24/9/2020	9:00	Bayswater Pit	0.55	106.5	0.03	91.8	0.03	99.4	0.36	109.7
29/9/2020	13:03	Bayswater Pit	1.51	110.3	0.07	96	0.05	106.4	0.85	110.7
30/9/2020	12:56	Entrance Pit	0.27	97.4	0.01	100.2	0.02	84.8	0.1	96.4